

CPR Plumbing

(210) 491-2777

05/24/10

PO Box 11, Helotes, TX 78023

Fax- 210-646-0086

cprplumbing1@aol.com

JOB#: 49000
NAME: HAPPY HOMEOWNER
ADDRESS: 123 STREET
SAN ANTONIO, TX
CLAIM#: 2045569
TEST DATE: 05/23/10

TUB WASTE AND OVERFLOW

For this report, a static test of the waste and overflow is described as:

Static testing of the tub waste and overflow is performed by removing the overflow plate from the tub and running the testing equipment down the waste and overflow drain. It is then filled with water and monitored for a period of 30 minutes. A drop in water level indicates that a leak is present. This does not necessarily mean that any water is lost under normal conditions. The P trap is not included on this test. The downstairs or one-story home tub waste and overflow is tested below grade only and can be tested above the finished floor upon request, however this may require opening walls.

TEST #1 INCLUDES: BATH #1 TUB	TEST #2 INCLUDES: BATH #2 TUB
1 MIN _____"	1 MIN _____"
5 MIN _____"	5 MIN _____"
10 MIN _____"	10 MIN _____"
15 MIN _____"	15 MIN _____"
20 MIN _____"	20 MIN _____"
30 MIN <u>0</u> "	30 MIN <u>0</u> "
60 MIN _____"	60 MIN _____"
OUT OF SIGHT _____	OUT OF SIGHT _____
WOULD NOT FILL _____	WOULD NOT FILL _____

NOTES: BOTH BATH #1 AND BATH #2 TUB WASTE AND OVERFLOW TEST HELD.